

CONTENTS

PREFACE

ACKNOWLEDGEMENT

	PAGE NO.
CHAPTER – I INTRODUCTION & OVERVIEW OF LITERATURE	1 - 29
1.1 CONSTRUCTING A 3-SIGMA CONTROL CHART	8
1.2 SHEWART CHARTS	14
1.3 CUMULATIVE SUM CHART (CUSUM)	15
1.4 POINEERS IN QUALITY CONTROL	16
1.5 REVIEW ON CUSIM CHART	17
1.6 REVIEW ON CHANGE POINT METHOD	26
1.7	
CHAPTER – II CONTROL CHARTS AND CUSUMS UNDER LINEAR TREND WITH RAYLEIGH DISTRIBUTIONS	32 - 66
2.1 INTRODUCTION	27
2.2 SHEWART CONTROL CHART WITH ACTION LINES	31
2.3 SHEWART CONTROL CHART WITH WARNING LINES	32
2.4. TRANSITION MATRICES FOR CONTROL CHARTS AND CUSUSMS WITH RAYLEIGH DISTRIBUTION	32
2.5 CONCLUSIONS	65

CHAPTER – III CONTROL CHARTS AND CUSUMS 67 - 92
UNDER LINEAR TREND WITH
LOG-LOGISTIC DISTRIBUTIONS

3.1	THE IMPORTANCE OF LOG-LOGISTIC DISTRIBUTION	67
3.2	RUN LENGTH CALCULATION UNDER LINEAR TREND WITH LOG-LOGISTIC DISTRIBUTION	69
3.3	RUN LENGTH PROPERTIES OF STANDARD CONTROL CHARTS UNDER LINEAR TREND WITH LOG-LOGISTIC DISTRIBUTION	89
3.4	CONCLUSIONS	92

CHAPTER – IV CONTROL CHARTS AND CUSUMS 93 - 116
UNDER LINEAR TREND WITH
ERLANG DISTRIBUTIONS

4.1	THE IMPORTANCE OF ERLANG DISTRIBUTION	93
4.2	RUN LENGTH CALCULATION UNDER LINEAR TREND WITH ERLANG DISTRIBUTION	94
4.3	RUN LENGTH PROPERTIES OF STANDARD CONTROL CHARTS UNDER LINEAR TREND WITH ERLANG DISTRIBUTION	114
4.4	CONCLUSIONS	116

CHAPTER – V CHANGE POINT METHOD WITH 117 -141
VARYING DISTRIBUTIONS

5.1	INTRODUCTION	117
5.2	CAHANGE POINT METHOD	118
5.3	IMPLEMENTATION OF CHANGE POINT METHOD	119
5.4	CAHNGE POINT METHOD WITH RAYLEIGH DISTRIBUTION WHEN THE PARAMETERS ARE NOT KNOWN.	121
5.5	PERFORMANCE OF THE CHANGE POINT APPROACH WITH RAYLEIGH DISTRIBUTION	129
5.6	PERFORMANCE OF THE CHANGE POINT MODEL WITH LOG-LOGISTIC DISTRIBUTION	134
5.7	CONCLUSIONS	140

REFEREMCES

i - x